

## Glensanda Harbour

NOTICE TO MARINERS 12/20

2<sup>ND</sup> December 2020

Due to silt deposit, with immediate effect the certified depth alongside Glensanda Loading jetty is reduced to 11.6m CD. Vessels at the jetty must maintain a minimum underkeel clearance of 0.6m at all times. Draft should be monitored at all stages of loading, and particularly if on deep draft over periods of low tide.

This restriction will remain in effect until notified otherwise. Measures are being taken to restore the full cleared depth of 12.3m CD.



I.F.Henry  
Harbour Master